



4	SLEEVE	1	BRASS	NICKEL	UNLESS OTHERWISE SPECIFIED 1.REMOVE ALL BURRS. 2.BREAK ALL CONNERS & EDGES CO.15 MAX. 3.CHAMFER 1ST & LAST THREADS 45°. 4.DIAMETERS ON COMMON CENTERS. TO BE CONCENTRIC WITHIN 0.1 T.I.R. 5.ALL DIMENSIONS ARE AFTER PLATING.	* MAJOR DIMENSION UNLESS OTHERWISE NOTED TOLERANCES 0.5-6=±0.2 6-30=±0.4 30-120=±0.6 120-315=±1.0 ANGLES=±1°			APPROVED	Paul						
3	INSULATOR	2	TEFLON	NONE					CHECKED	Danny		TITLE	QMA JACK TO N JACK			
2	PIN	1	BRASS	GOLD					DRAWN	Andrew		DRAWING NO.	ADAPT-QMAF-NTYPEF	REV	A	
1	BODY	1	BRASS	NICKEL					SCALE	3/1	UNIT	MM	DRAWN DATE	02/06/24	FILE NO.	
NO	Description	Q'ty	Material	Finish												