



Enabling Industrial IoT

SNYPER-LTE Graphyte

Case Contents

- 1 SNYPER-LTE Graphyte with support cradle underneath
- 2 PSU with 4 adapter heads
- 3 2x USB cables - 0.5m and 1.8m
- 4 USB Car Charger
- 5 Omni-directional Antennas - General Purpose (Black) and 2600MHz (Silver/Grey)
- 6 Directional Antenna
- 7 Extension Cable for Directional Antenna
- 8 Tripod

GRAPHYTE CASE CONTENTS



SNYPER·LTE GRAPHYTE QUICK

START GUIDE

FIRST STEP BEFORE USE

1. BATTERY CHARGE: Charge the unit for 4-6 hours or until the red charge light is extinguished
2. SOFTWARE REVISION: Go to www.siretta.com/software-library to check for latest software
 - Click on the "(V3)" tab
 - Compare website revision to that in the SNYPER's "ABOUT" menu (this can be accessed from the "MAIN MENU")
 - Upgrade the software accordingly, following the procedure in the SNYPER-LTE Graphyte manual <https://www.siretta.com/products/cellular-network-analysers/4g-lte-analyser-network/snyper-lte-graphyte-eu/>
3. SETTING TIME: Power up the SNYPER. From "MAIN MENU" select "Setup" > "Set Time". Use the keypad arrows to set date/time so you can timestamp your surveys. You are now ready to go.



POWER ON TO BRING UP MAIN MENU SELECTIONS

SURVEY

NEW SURVEY OPTIONS

- 1) Select Full, LTE, UMTS or GSM
- 2) Select number of cycles and time interval
- 3) Connect charger to extend surveys
- 4) Press to start survey
- 5) Leave device to complete surveys

POST SURVEY OPTION 1

- 1) Select Show Results
 - 2) Press for liveSCAN
- Use key to exit

POST SURVEY OPTION 2

- 1) Select Show Summary
- Use key to exit

POST SURVEY OPTION 3

- 1) Select Save Results
- This is only necessary if Auto Save is off
- Use key to exit

SAVED RESULTS

STORED SURVEY

- 1) Select results file you wish to view
 - 2) Select Show Results, Show Summary, or Export Results
- Use key to exit



SETUP

- Language: ENG/DEU/FRA/ITA/SPA
Display: Screen brightness and text colours
Auto off: Auto switch off and dimming
Documents: Results file types and Auto Save
Sound: On/Off
System: Mode and region of operation
Set Time: Set date and time
Factory Reset: Return to default settings
- Use key to exit

ABOUT

- Key reference parameters about the device
- Use key to exit

PC CONNECT

- PC CONNECT
- 1) Connect USB cable between device and PC
 - 2) Select ON to enable USB connection, begin results download
 - 3) Copy files required to PC
 - 4) Select OFF to disable connection
- Use key to exit
- You can then view results files on your PC

For more detailed information,
please visit our website at www.siretta.com