



7	GASKET	1	SI-RUBBER	ORANGE
6	RETAINING RING	1	BRASS	NICKEL
5	SHELL	1	BRASS	NICKEL
4	GROUND RING	1	BRASS	NICKEL
3	INSULATOR	2	TEFLON	NONE
2	PIN	2	BRASS	GOLD
1	BODY	2	BRASS	NICKEL
NO	Description	Qty	Material	Finish

UNLESS OTHERWISE SPECIFIED 1.REMOVE ALL BURRS. 2.BREAK ALL CONNERS & EDGES CO.15 MAX. 3.CHAMFER 1ST & LAST THREADS 45°. 4.DIAMETERS ON COMMON CENTERS. TO BE CONCENTRIC WITHIN 0.1 T.I.R. 5.ALL DIMENSIONS ARE AFTER PLATING.	* MAJOR DIMENSION			APPROVED	Paul
	UNLESS OTHERWISE NOTED TOLERANCES 0.5-6=±0.2 6-30=±0.4 30-120=±0.6 120-315=±1.0 ANGLES=±1°			CHECKED	Danny
	SCALE	3/1	UNIT	MM	DRAWN
				DRAWN DATE	02/06/02

		TITLE	QMA JACK TO N PLUG	
		DRAWING NO.	ADAPT-QMAF-NTYPEM-RA	REV
FILE NO.				